


Service Bulletin

Reference Number	NBP-0002
Date	8/22/2018
Product	Digital Pump
Affected Models	NPR6Di & NPR8Di

If any residual refrigerant encounters the micron sensor, it may produce erroneous readings.

Issue: Display on micron gauge is reading incorrectly.

Solution: Press and hold the Start/Stop  button for 3 secs to “zero” out gauge.



This material is published for informational purposes only and intended for use only by persons qualified for the specific tasks shown. Qualified personnel are those who, based on their training and experience, are capable of identifying risks and avoiding possible hazards when handling or servicing a product. Only qualified personnel should repair products powered by electricity. Any attempt to handle, service or repair the product or products by anyone other than qualified personnel could result in serious injury or death. You agree that your use of and dependence on this information is at your sole risk. This information is subject to change or update without notice. There are no warranties, either expressed or implied, regarding the accuracy or completeness of this information.